

THE WORLD SPA APARTMENT OWNERS ASSOCIATION, SEC. 30/41, GURUGRAM

Bill of Quantity For Cracks repair work on Driveway (West & East side)
--

Sl.No	Work Description	UOM	Qty. approx	Rate	Amount
1	Cleaning & chipping out of bitumen from the existing cracks including making of proper uniform edge by edge cutting machine, using blower for dust free surface before filling any material. (Rate is only for 25*25mm wide groove, if the width of groove increase, then for every 25mm it will be converted to rmt & same will be claimed).	RMT	3000		
2	Providing and application of ready to use pre polymer based formulated crack repairing compound including final grinding of repaired surface. Traffic can be open after 6 hours of work. (Rate is only for 25* 25mm wide groove, if the width of groove increase then for every 25mm it will be converted to rmt & same will be claimed). (Product- Cemek)	RMT	3000		
				Total Amount	
				GST 18%	
				Amount with GST	

Note :- 1. Final Payment As per actual Measurement.

is only for upto 25mm wide groove, if the width of groove increase then for every 25mm it will be converted to rmt & same will be cl

		
Sr. Executive Civil	Technical Manager	Estate Head
Gaurav Dagar	Udairaj Singh	Harpreet Singh

		
Manish Choudhary	Mr Santosh Agarwal	Ms. Myrrelle Machado
AMPSL SME 10/15/2018	Infra Committee	Authorised BOM