

RFP for Seepage Audit at The World Spa, Gurgaon

- Visual Inspection of Building Fabric for identification of Seepage/leakages and other defects.
- Collect photographic and video evidence of seepage for documentation and analysis.
- Review available building plans and construction documents to understand the building's structure and plumbing systems.
- Detailed study of the expansion joints and the treatment done on the Expansion joints.
- Preparation of sang list in respect to the abnormalities observed during the Inspection
- Recommendation in respect to the treatment to be done to arrest the seepage/leakages
- Preparation of BOQ for repair and Maintenance work.
- Providing recommendation on the material to be used for repair and Maintenance work.
- Estimation of Time & cost involved in the Repair & Maintenance work.

Please provide quotation for seepage analysis with BOQ and RFP.